

1/4




FIG. 1

V1	_____	F
V2	_____	G MAX
V3	_____	3/4G MAX
V4	_____	1/2G MAX
V5	_____	1/4G MAX
V6	_____	V _C = 0
V7	_____	-1/4G MAX
V8	_____	-1/2G MAX
V9	_____	-3/4G MAX
V10	_____	-G MAX
V11	_____	-F

FIG. 2

000025 11501

2/4




FIG. 3




FIG. 4

3/4




FIG. 5




FIG. 6

000005 11201
 10621 55036660

FIG. 7

FIG. 8